



1 mm added to ideal length
Socket position may be wrong

